

# Oil Field Environmental Incident Summary

**Incident:** 20140706174418      **Date/Time of Notice:** 07/06/2014 17:44  
**Responsible Party:** BOREJAKS ENERGY SERVICES  
**Well Operator:** BOREJAKS ENERGY SERVICES  
**Well Name:** NYGAARD SWD 1  
**Field Name:** RAWSON      **Well File #:** 90216  
**Date Incident:** 7/2/2014      **Time Incident:** 13:00      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 150      **Rng:** 101      **Sec:** 14      **Qtr:**  
**Location Description:**

**Submitted By:** Kim Reister      **Received By:**  
**Contact Person:** Kim Reister  
520 CENTRAL PARKWAY EAST  
SUITE 107  
PLANO, TX 75074

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Feet  
**Distance Nearest Water Well:** 500 Feet

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site      **Reported to NRC:** Yes  

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

<b>Oil</b>	<b>10</b>	<b>Gallons</b>	<b>10</b>	<b>Gallons</b>		
------------	-----------	----------------	-----------	----------------	--	--

<b>Brine</b>	<b>10</b>	<b>Barrels</b>	<b>10</b>	<b>Barrels</b>		
--------------	-----------	----------------	-----------	----------------	--	--

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**

**Risk Evaluation:**

No immediate health hazards.

**Areal Extent:**

**Potential Environmental Impacts:**

No likelihood of any impact to surface water or groundwater. Some soil on facility site was affected.

**Action Taken or Planned:**

Spill was contained on site. Any residual brine/oil was cleaned up. Scoria replaced. Adding rock catcher to offload lane to ensure no objects get through that could become lodged in valves again.

**Wastes Disposal Location:** Tervita

**Agencies Involved:****Updates**

---

**Date:** 7/6/2014      **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to an on-location valve/pipeline leak, remained on location according to the report. NDIC retains oversight.

---

**Date:** 7/11/2014      **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

The weather was 69°F; clear, with wind from the northwest 10-15 mph. I followed up due to an e-mail received through the National Response Center. I talked to personnel for the site and received the following information. The site has pits under loading area that are emptied with sumps into the injection system. The pits collect both overflow and storm water runoff. There was no indication of any of the spill leaving the site. The site is well maintained. No further followup is needed at this time.